

CERTIFICATE OF COMPLIANCE

Certificate Number 20160402-E319860
Report Reference E319860-20080306
Issue Date 2016-April-02

Issued to: COPRECI S COOP LTDA
AVDA DE ALAVA 3
APARTADO 62
ARETXABAETA
20550 GUIPUZCOA SPAIN

**This is to certify that
representative samples of**

COMPONENT - INCOMPLETE ROTATING MACHINES
AND ROTATING MACHINE PARTS

Motor part models BLP3, BLP3.01, BLP3.02, BLP3.03,
BLP3.04, BLP3 TYPE 1, BLP3 TYPE 2, BLP3 TYPE 3.

Have been investigated by UL in accordance with the
Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL 1004-1 - Rotating Electrical Machines – General
Requirements
.CSA C22.2 NO. 100 - Motors And Generators

Additional Information: See the UL Online Certifications Directory at
www.ul.com/database for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's
Certification and Follow-Up Service.

Recognized components are incomplete in certain constructional features or restricted in performance
capabilities and are intended for use as components of complete equipment submitted for investigation rather
than for direct separate installation in the field. The final acceptance of the component is dependent upon its
installation and use in complete equipment submitted to UL LLC.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Assistant Chief Engineer, Global Inspection and Field Services

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please
contact a local UL Customer Service Representative at www.ul.com/contactus

